



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Report Date December 2, 2005

Supervisor AOA

Mine Name: Mill'a Martinique
Operator Name: Martinique Mining

Permit number: S/017/046
Inspection Date: September 13, 2005
Time: 3:30-3:45 PM

Inspector(s): Paul Baker
Other Participants: Buzz Rakow (Hanksville BLM)
Mine Status: Regraded

Weather: Mostly clear, 70's

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
The operator requested release.

Inspection Summary:

2. Public Safety (shafts, adits, trash, signs, highwalls)

Since this was my first visit to the site, I was not personally familiar with previous conditions, but Mr. Rakow was impressed with how much cleanup work had been done. Pictures from three years ago show several pieces of equipment, old barrels, hoses, PVC pipe, and other items that have now been removed.

7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)

Grading has been completed. The site is basically flat.

8. Water Impoundments

The pond, an irrigation ditch, and a culvert, although apparently used for this operation, have been present for some 30-40 years and are used for grazing.

10. Revegetation

It does not appear the site was seeded. Vegetation consists primarily of halogeton (a poisonous weed) with some snakeweed and rabbitbrush.

Inspection Date: September 13, 2005; Report Date: December 2, 2005

Page 2 of 2

S/017/046

12. Other

I took GPS data along a short access road and at a point at the mine site. A copy of the map is attached to this report.


Conclusions and Recommendations:

The site needs to be prepared and seeded this fall. The area should be roughened, and the Division recommends either ripping or using a trackhoe to make pock marks. This helps to harvest water for use by plants.

Immediately after the site is roughened, it should be seeded. There is a letter dated August 24, 2003, where the BLM specifies a seed mix containing galleta, fourwing saltbush, Indian ricegrass, crested wheatgrass, and winterfat.

The ditch, culvert, and pond are used to water cattle, and Mr. Rakow said they should remain for the postmining land use.

Inspector's Signature



Date: December 2, 2005

PBB:jb

cc: Kim Wilson, Martinique Mining

Buzz Rakow, Hanksville BLM

Attachment: GPS Map & Photo Attachment

ATTACHMENT
Photographs

S/017/046, Mill'a Martinique, Martinique Mining

Inspection Dated: September 13, 2005; Report Dated: December 2, 2005



Photo 1. All of these photos are views of the regraded site.
Note that the equipment and other items have been removed
and that the site blends with surrounding areas.




Photo 2.



Photo 3. The pond is just beyond the nearer tall brush.



Photo 4.



Mine Number: S0170046
Mine Name: Milla Martinique
Township 31 S Range 11 E Section 25 SLBM


Inspection Date Sept. 13, 2005
Map Produced by DKS

Acres Disturbed	0
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	0
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
All items symbolized in legend may not be appear on map

- County Boundary
- Access
- Mine
- NonMine
- Other
- Interstate
- US Route
- State Route
- Primary Route
- Secondary Route
- Main Dirt Road
- Unimproved Road
- Interchange
- Trail
- Township or range line: location doubtful
- Section line
- Section line: location doubtful
- Disturbed
- Regraded
- Seeded
- Released
- Excluded
- PreExisting
- Prelaw
- Bond Area
- SITLA Mineral Leases
- BLM Leases
- Community Pk

DOQ imagery date 1993



0 625
Feet

1:7,500 1 inch equals 625 feet

Verify Scale

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program